

# BOP.BAS.020 Immediate reaction to a safety problem

*Regulation (EU) 2020/357*

The operator shall implement:

1. safety measures mandated by the competent authority in accordance with paragraph (c) of point ARO.GEN.135 of Annex II (Part-ARO) to Regulation (EU) No 965/2012; and
2. airworthiness directives and other mandatory information issued by the Agency in accordance with paragraph (h) of Article 77(1) of Regulation (EU) 2018/1139.

[BOP.BAS.025 Designation as pilot-in-command](#)

From:

<https://www.balloonwiki.org/luftrecht/> - **Ballaeron - wo steht das?**

Permanent link:

<https://www.balloonwiki.org/luftrecht/doku.php/en/bop.bas/020>

Last update: **2024/02/24 15:53**

