

# ML.A.902 Validity of the airworthiness review certificate

Regulation (EU) 2019/1383

1. An ARC becomes invalid if, alternatively:
  1. it is suspended or revoked;
  2. the airworthiness certificate is suspended or revoked;
  3. the aircraft is not in the aircraft register of a Member State;
  4. the type certificate under which the airworthiness certificate was issued is suspended or revoked.
2. An aircraft shall not fly if the ARC is invalid or if any of the following circumstances are present:
  1. the continuing airworthiness of the aircraft or any component fitted to the aircraft does not meet the requirements of this Annex;
  2. the aircraft does not remain in conformity with the type design approved by the Agency;
  3. the aircraft has been operated beyond the limitations of the approved flight manual or airworthiness certificate, without appropriate action being taken;
  4. the aircraft has been involved in an accident or incident that affects the airworthiness of the aircraft, without subsequent appropriate action to restore airworthiness;
  5. a modification or repair to the aircraft or any component fitted to the aircraft is not in compliance with Annex I (Part-21) to Regulation (EU) No 748/2012.
3. Upon surrender or revocation, the ARC shall be returned to the competent authority.

→ [ML.A.903](#)

From:

<https://www.balloonwiki.org/luftrecht/> - **Ballaeron - wo steht das?**

Permanent link:

<https://www.balloonwiki.org/luftrecht/doku.php/en/part-ml/a.902>

Last update: **2023/09/03 08:20**

